


IN THE DRAWINGS

The enclosed replacement drawing sheet is intended to replace the original sheet of Figure 3. In Figure 3, applicant corrects a typo in the part number of the I/O addresses as shown in the enclosed mark up of Figure 3 as indicated in the enclosed annotated drawing sheet. Figure 6 and paragraph 0026 of the published specification support the I/O addresses should be part number 91.

1
2
3
4
5
6
7
8
9
0
1
2
3
4
5
6
7
8
9
0
1
2
3
4
5
6
7
8
9
0

Respectfully Submitted,



Robert Moll
Reg. No. 33,741

1173 St. Charles Court
Los Altos, CA 94024
Tel: 650-567-9153
Fax: 650-567-9183
Email: rgmoll@patentplanet.com

Robert Moll
Robert Moll
Reg. No. 33,741

1173 St. Charles Court
Los Altos, CA 94024
Tel: 650-567-9153
Fax: 650-567-9183
Email: rgmoll@patentplanet.com



Annotated Sheet




FIGURE 3